


M12
maschio/male



Loop Powered: 1(+) / 2 (-)

IO-Link; 1(+) / 3 (GND) / 4 (IO-Link)

Switch.Out: 1(+) / 3 (GND) / 4 (out)